

# Activejet®

## AB-3213MN

Compatible inkjet cartridge Replacement for Brother Brother LC3213M



|                                       |   |
|---------------------------------------|---|
| <b>Quantity per pack</b>              | 1 pc(s)   |
| <b>Printing colours</b>               | Magenta   |
| <b>Brand compatibility</b>            | Brother   |
| <b>Print technology</b>               | Inkjet printing   |
| <b>Cartridge capacity</b>             | Standard Yield  |
| <b>Colour ink cartridges quantity</b> | 1   |
| <b>Colour ink volume</b>              | 7 ml  |
| <b>Quantity per box</b>               | 1 pc(s)   |
| <b>Type</b>                           | Compatible  |
| <b>Operating temperature (T-T)</b>    | -20 - 40 °C   |
| <b>Package type</b>                   | Box   |
| <b>Technology</b>                     | New   |
| <b>Version</b>                        | Supreme   |
| <b>Supply type</b>                    | Single pack   |
| <b>Certification</b>                  | ISO 9001, ISO 14001, ISO 27001, ISO 28000, TÜV Rheinland (ISO/IEC 19752, ISO/IEC 19798), CE |
| <b>Product description</b>            | Activejet Ink Cartridge   |
| <b>Sustainability certificates</b>    | CE  |
| <b>Black ink type</b>                 | Dye-based ink   |
| <b>Compatibility</b>                  | Brother DCP: J572DW, J772DW, J774DW. Brother MFC: J491DW, J497DW, J890DW, J895DW.           |
| <b>Replacement for</b>                | LC-3213M  |
| <b>OEM code</b>                       | Brother LC3213M   |
| <b>Hazard pictogram(s)</b>            | GHS07: Harmful  |

|                            |                             |
|----------------------------|-----------------------------|
| <b>Hazard pictogram(s)</b> | GHS09: Environmental hazard |
| <b>Warnings</b>            | Do not inhale vapours.      |
| <b>EAN</b>                 | 5901443119074               |