




# ACC-581PBNX

Compatible inkjet cartridge Replacement for Canon Canon CLI-581PBXXL



|                                       |   |
|---------------------------------------|---|
| <b>Quantity per pack</b>              | 1 pc(s)   |
| <b>Cartridge capacity</b>             | High (XL) Yield   |
| <b>Colour ink cartridges quantity</b> | 1   |
| <b>Brand compatibility</b>            | Canon   |
| <b>Colour ink volume</b>              | 11.7 ml   |
| <b>Printing colours</b>               | Photo blue  |
| <b>Type</b>                           | Compatible  |
| <b>Technical features</b>             | Cartridge with chip   |
| <b>Ink type</b>                       | Dye-based ink   |
| <b>Class</b>                          | A+  |
| <b>Replacement for</b>                | Canon   |
| <b>Technology</b>                     | New   |
| <b>Compatibility</b>                  | Canon Pixma: TS8150, TS8151, TS8152, TS8250, TS8251, TS8252, TS9150, TS9155.                |
| <b>Compatible ink types, supplies</b> | CLI-581XL   |
| <b>Version</b>                        | Supreme   |
| <b>Supply type</b>                    | Single pack   |
| <b>Certification</b>                  | ISO 9001, ISO 14001, ISO 27001, ISO 28000, TÜV Rheinland (ISO/IEC 19752, ISO/IEC 19798), CE |
| <b>Product description</b>            | Activejet Ink Cartridge   |
| <b>Colour ink type</b>                | Dye-based ink   |
| <b>OEM code</b>                       | Canon CLI-581PBXXL  |
| <b>Hazard pictogram(s)</b>            | GHS07: Harmful  |

---

|                            |                             |
|----------------------------|-----------------------------|
| <b>Hazard pictogram(s)</b> | GHS09: Environmental hazard |
| <b>EAN</b>                 | 5901443110606               |