



# AEB-712N

Compatible inkjet cartridge Replacement for Epson Epson T0712, T0892, T1002



<b>Quantity per pack</b>	1 pc(s)
<b>Certification</b>	ISO 9001, ISO 14001, TUV (ISO/IEC 19752, ISO/IEC 19798), CE
<b>Printing colours</b>	Cyan
<b>Print technology</b>	Inkjet printing
<b>Cartridge capacity</b>	High (XL) Yield
<b>Colour ink cartridges quantity</b>	1
<b>Brand compatibility</b>	Epson
<b>Colour ink volume</b>	15 ml
<b>Compatibility</b>	Epson Stylus: D78, D92, D120, DX4000, DX4050, DX4400, DX4450, DX5000, DX5050, DX6000, DX6050, DX7000F, DX7400, DX7450, DX8400, DX8450, DX9400F, S20, S21, SX100, SX105, SX110, SX115, SX200, SX205, SX210, SX215, SX218, SX400, SX405, SX410, SX415, BX300F, SX510W, SX515W, SX600FW, B40W, BX310FN, BX600FW, BX610FW.
<b>Type</b>	Compatible
<b>Package type</b>	Box
<b>Class</b>	A+
<b>Technology</b>	New
<b>Version</b>	Supreme

<b>Replacement for</b>	Epson
<b>Compatible ink types, supplies</b>	T0712; T0892; T1002;
<b>Product description</b>	Activejet Ink Cartridge
<b>OEM code</b>	Epson T0712, T0892, T1002
<b>Colour ink page yield</b>	480 pages
<b>Hazard pictogram(s)</b>	GHS07: Harmful
<b>Hazard pictogram(s)</b>	GHS09: Environmental hazard
<b>EAN</b>	5904356294388