

# Activejet®

## ATH-59NX

Laser toner replacement for HP HP 59X CF259X



<b>Print technology</b>	Laser printing
<b>Built-in drum unit</b>	Yes
<b>Quantity per pack</b>	1 pc(s)
<b>Black toner cartridges quantity</b>	1
<b>Printing colours</b>	Black
<b>Brand compatibility</b>	HP
<b>Cartridge capacity</b>	High (XL) Yield
<b>Black toner page yield</b>	10000 pages
<b>Storage temperature (T-T)</b>	-20 - 40 °C
<b>Type</b>	Compatible
<b>Package type</b>	Box
<b>Technology</b>	New
<b>Version</b>	Supreme
<b>Supply type</b>	Single pack
<b>Certification</b>	ISO 9001, ISO 14001, ISO 27001, ISO 28000, TÜV Rheinland (ISO/IEC 19752, ISO/IEC 19798), CE
<b>OEM code</b>	HP 59X CF259X
<b>Additional information</b>	Toner with chip
<b>Sustainability certificates</b>	CE
<b>Additional information</b>	NOTE: We recommend disable printer software updates, the new update may cause problems with the proper operation of the toner.

<b>Compatibility</b>	HP LaserJet Pro: M304a, M404, M404dn. HP LaserJet: M406Dn, M406 Enterprise. HP LaserJet MFP: M430 Enterprise. HP LaserJet Pro MFP: M428.
<b>Toner with Chip</b>	Y
<b>Hazard pictogram(s)</b>	GHS07: Harmful
<b>Hazard pictogram(s)</b>	GHS09: Environmental hazard
<b>Warnings</b>	Do not inhale toner dust.
<b>EAN</b>	5901443114987